

9A39

Please  
Send  
TO:**Employee Locator**  
query by name

<b>Name</b> WAKS JOSEPH <b>Employee No</b> 73742 <b>Organization</b> P/2834--GROUP ART UNIT 2834 <b>Email</b> joseph.waks@uspto.gov <b>System Login Id</b> jwaks								
Primary	Bldg	Floor	Suite	Corr.	Room	Zone	Planned Move	Status
*	JEF	09		A	61			Current
<b>CONTACT NUMBER</b>								
Primary	Type	Number			Ext	Planned Move	Status	
*	Telephone	(571)272-2037					Current	

[To correct or add information displayed click here](#)

Please identify serial number and  
Send to IFW Scanning.

09 981 231  
Bldg App.

06/07/05

RECEIVED  
CENTRAL FAX CENTER

JAN 05 2006

Dear Joseph Wak,

It has come to my attention that an oversight must have occurred with the schematic drawing I submitted to you. The drawing that was sent to you does not reflect an accurate representation of my invention. Enclosed is an accurate representation of my invention. Note Changes:

- 1) Note arrow pointed upward to the surface
- 2) Note lower water pressure existing from the system.
- 3) Note higher water pressure entering the system at the bottom of the system.

Please note the correction and give me FEED back ASAP

Respectfully yours,

Maurice Dudley  
Fx Tel 4046997938  
1330 New Hope Rd  
Atl.Ga 30331

Fig. 1

